


N ←

Damaged exterior door

Foundation crack



garage

HOUSE

Decayed
facia

Crawlspace
access

FRONT



Ferndale